

CERTIFICATE OF COMPLIANCE

Certificate Number E530444
Report Reference E530444 - 20221014
Issue Date 2022-OCTOBER-14

Issued to: Villareal Division Equipos S.A DE C.V
Calle Morelos Sur 905, Colonia Centro
Allende, Nuevo León, 67350 MX

**This certificate confirms that
representative samples of**

Incomplete Rotating Machines and Rotating Machine Parts
- Component

See Addendum Page for Models

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 1004-1 - Rotating Electrical Machines - General Requirements
CSA C22.2 No. 100 - Motors and Generators

Additional Information: See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E530444
Report Reference E530444 - 20221014
Issue Date 2022-OCTOBER-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model(s) - MSAE4 1.51230, MSAE4 1.512302H, MSAE4 1.53230, MSAE4 1.53460, MSAE4 1/21127
MSAE4 1/211272H, MSAE4 1/21230, MSAE4 1/212302H, MSAE4 1/23230, MSAE4 1/23460
MSAE4 103230, MSAE4 103460, MSAE4 11127, MSAE4 11230, MSAE4 112302H, MSAE4 13230
MSAE4 13460, MSAE4 21230, MSAE4 31230, MSAE4 23230, MSAE4 23460, MSAE4 3/41230,
MSAE4 3/412302H, MSAE4 3/43230, MSAE4 3/43460, MSAE4 33230, MSAE4 33460, MSAE4 51230
MSAE4 53230, MSAE4 53460, MSAE4 7.53230, MSAE4 7.53460.



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>

